

CONTINUOUS DRAINAGE SYSTEM NOT FULLY REPRESENTED IN PLANS


Project → Multi-Property Flow → Municipal → River

A - CITY GIS (INCLUDING HYDRO 2001)




250-RICR-150-15
§1.4 §1.6 §1.17
Cranston Code §13.04

B - APPLICANT PLAN



F - CERTIFIED SURVEY



G - RIDOT MAINTENANCE (MANHOLE 11578)




C - MUNICIPAL DRAINAGE




D - FIELD PHOTOS (FLOW PATH)



Area Subject to Storm Flowage (ASSF)



Drainage Conveyance Path Not Shown
Road A - Primary Access



Drainage Feature (Surveyed)
Shown in Certified Class III Existing Conditions Survey



Exhibit A: CRANSTON CITY GIS (INCLUDING HYDRO 2001)



EXHIBIT A: CRANSTON CITY GIS (NOT INCLUDING HYDRO 2001)












NATURE? POSSUM · BEAVER · SKUNKS
 EAGLE · OWL · TURKEY · HAWKS · ROBINS · FOX
 SNAKES · COYOTE · BEAR · CARDINALS · RABBITS



CULVERT - ACTIVE BROOK?
 SEISMIC ACTIVITY · HOUSES SHAKE